

## **SERVICE BULLETIN**

Product :	Refrigerator	Bulletin No.	2010-Ref-02
Model :	RSH ** model	Bulletin Date :	2010/03/30
Buyer :	All	ECN No.	: -

## **SUBJECT: No cooling(Icing up)**

## **Background**


Ice forming at the top of the refrigerator evaporator around the suction tube/capilary pipe where it emerges from liner.





## **Cause**

- Suction pipe is touching the liner this can causes dew condensation to form on top left area of evap cover
- Ice ball formation expands around the top left area of evaporator.
- Symptoms are excessive fan noise and no cooing.



Application	Reference (	), Only	Defected s	ets (O)	), Whole sets	( )						
Attachment	Schematic I	Diagram (	),	Mechanical	Diagram (	),	None (	),	Others (	),	Applied Model (	)
Product Month :		All							Serial	No.	(~ from)	
Published by	:	J.Y Kim			Checked by	:N.Y	' Jeun				Approved by :	S.J Shin

Step	Description	Used Part
1	Adjust defrost off temperature refer to Main bulletin	-
2	Disassemble cover evap	-
3	Move the defrost sensor from it's original position as shown below.	Defrost sensor Fixer Sensor
4	Replacement of Seal cover Evap R/L Remove seal damaged from water and then attach new seal	SEAL CUT OJC
5	Assemble Support Cover Evap on deodorizer part  SUPPORT  COVED EVAD  Foam-lex 7T	ASSY SUPT-Cover EVAP L ASSY SUPT-Cover EVAP R
6	Re-assemble Cover Evap	-