

### Important Notes (3103 309 05391)

CD Drives MCD2 (3103 308 0538x) or MCD1B (3103 309 0535x) are no longer available.  
 If you order above CD Drive and we deliver CD Drive DA12T3 (3103 308 05391) instead,  
 please follow below instructions and change components on CD board of the sets brought in for repair.

AZ2558, MC-M250		FW-M355, FWM390, FWM399, FWM570, FWM730		MCM5, MCM7, MCM8	
2813	CER2 0603 X7R 50V 4N7	2807	CER1 0603 NP0 50V 180P	2812	Deleted
2815	CER1 0603 NP0 50V 100P	3723	RST SM 0603 47K PM5	3831	RST SM 0603 10K PM5 (added)
2835	CER2 0603 X7R 50V 2N2	3800	RST SM 0603 47K PM5	3835	Deleted
2861	CER1 0603 NP0 50V 180P	3802	RST SM 0603 47K PM5	3853	RST SM 0603 6K8 PM5
3801	RST SM 0603 39K PM5	3811	RST SM 0603 47K PM5	4800	Deleted
3801	RST SM 0603 39K PM5	3820	RST SM 0603 4K7 PM5	4801	RST SM 0603 JUMP. 0R05
3803	RST SM 0603 47K PM5	3821	RST SM 0603 4K7 PM5	4802	RST SM 0603 JUMP. 0R05
3804	RST SM 0603 47K PM5	3822	RST SM 0603 4K7 PM5	4803	Deleted
3805	RST SM 0603 47K PM5	3838	RST SM 0603 10K PM5 (added)		
3806	RST SM 0603 47K PM5	3833	RST SM 0603 39K PM5		
3846	Deleted	3834	RST SM 0603 39K PM5		
3850	RST SM 0603 5K6 PM5	3836	RST SM 0603 1K2 PM5		
3853	RST SM 0603 1K2 PM5	3844	RST SM 0603 5K6 PM5		
3855	RST SM 0603 10K PM5 (added)	3883	RST SM 0603 680R PM5		
3862	RST SM 0603 680R PM5	3890	RST SM 0603 4K7 PM5		
3898	RST SM 0603 220R PM5	3891	Deleted		
3902	RST SM 0603 1K5 PM5				
3905	RST SM 0603 680R PM5				
3907	RST SM 0603 820R PM5				

