

Service
Service
Service

Product Service Group BG HENT

Service Information

Already published Service Informations:

Spare parts code no. for Service Category 1 & Over-the-Counter Exchange sets:

This publication gives a survey of service spare parts for those typenumbers for which no service manual has been published.

REMOTE

MODEL	CONTROL	AUDIO CABLE	VIDEO CABLE	AV CABLE	MAINS CABLE	MISCELLANEOUS
DVP3050V/37	9965 000 27557			9965 000 24112 9965 000 27558*		9965 000 27671 DVD Main CBA Unit 9965 000 27672 Combi MCV CBA 9965 000 27555 VCR Mechanism 9965 000 27556 DVD Loader Mech. 9965 000 09209 RF Cable
DVP3050V/37 (2nd Genration)						9965 000 28854 Combi MCV CBA (can use to replace 9965 000 27672) all other parts refer to predecessor
DVP3055V/01	9965 000 28017					9965 000 25543 RF Cable
DVP3055V/02	9965 000 28017					9965 000 25543 RF Cable
DVP3055V/05	9965 000 28017					9965 000 25543 RF Cable
DVP3055V/19	9965 000 28017					9965 000 25543 RF Cable
DVP3100V/01	9965 000 28018					9965 000 25543 RF Cable
DVP3100V/02	9965 000 28018					9965 000 25543 RF Cable
DVP3100V/05	9965 000 28018					9965 000 25543 RF Cable
DVP3100V/19	9965 000 28018					9965 000 25543 RF Cable
MDV456/17 2nd Generation	9965 000 26752			9965 000 24112 9965 000 27558*		9965 000 24157 Fuse T1A 250V
MDV560VR/17 2nd Generation	9965 000 23708	9965 000 23711	9965 000 23710		9965 000 27790 Mains Cord	9965 000 23709 RF Cable 9965 000 27786 VCR Mechanism 9965 000 27787 DVD Module - Zoran 9965 000 27788 Combi Board 9965 000 27789 Power Board 9965 000 27791 Main Key Board

* Alternative parts