



Kit de dépannage alimentation des châssis ICC5



35065850

Qté	Désignation	Position	
1	1 μ F 20% 63V	CL21	
1	100 μ F 20% 35V	CP04	
1	1000 μ F 40V	CP46	Selon modèle
1	1000 μ F 20% 16V	CL51	
1	100K 1% 0.40W	RL10*	Selon modèle
1	105K 1% 0.40W	RL10*	Selon modèle
1	110K 1% 0.40W	RL10*	Selon modèle
1	1A6T	FPO5	
1	2,2nF 10% 1KV	CP23	
1	2200 μ F 16V	CP46	Selon modèle
1	2200 μ F 35V	CL52	
1	220nF 20% 63V	CL19	
1	22K Adjust	PL15	
1	2SC5339	TP24	
1	3,3nF 10% 100V	CL16	
1	47 μ F 100V	CP24	
1	470 μ F 50V	CP26	
1	4700 μ F 20% 25V	CP37	
1	503KHZ Filtre ceramique	QL07	
1	76K8K 1% 0.40W	RL10*	Selon modèle
1	82K 2% 0.50W	RL10*	Selon modèle
1	BA157 / BY201	DP26	
1	BC337-40	TP11	
1	BC548C	TP15	
1	BD434	TP19	
1	BZX55B9V1	DP45	

