


This diagram illustrates the exploded view of a washing machine, showing the main body, door, and various internal components. The parts are labeled with numbers and codes, such as 030 0, 701 0, 781 0, 572 0, 902 1, 421 0, 490 0, 491 0, 502 0, 717 3, 717 5, 331 0, 622 0, 339 0, 335 0, 339 0, 620 4, 620 3, 621 0, 301 0, 653 0, 301 0, 034 2, 034 3, 332 0, 900 0, 583 0, 783 0, 753 1, 011 0, 794 5, 086 0, 084 0, 910 6, 053 0, 013 0, 630 0, 024 0, 001 0, 190 1, 190 0, 021 0, 190 2, 040 0, 144 0, 144 1, 932 0, 130 0, 130 1, 110 0, 141 0, 143 1, 030 0, 701 0, 781 0, 572 0, 902 1, 421 0, 490 0, 491 0, 502 0, 717 3, 717 5, 331 0, 622 0, 339 0, 335 0, 339 0, 620 4, 620 3, 621 0, 301 0, 653 0, 301 0, 034 2, 034 3, 332 0, 900 0, 583 0, 783 0, 753 1, 011 0, 794 5, 086 0, 084 0, 910 6, 053 0, 013 0, 630 0, 024 0, 001 0, 190 1, 190 0, 021 0, 190 2, 040 0, 144 0, 144 1, 932 0, 130 0, 130 1, 110 0, 141 0, 143 1, 143 0 { 110 0, 130 0, 130 1, 141 0, 143 1, 144 0, 144 1, 932 0. A box at the bottom left contains the number 8584 407 29000.

VUE ECLATEE



8584 407 29000