⇒ ərçelik	PART - GROUP CHANGE NOTIFICATION				Bulletin no:2010-12			01.03.20	010	
	Prepared by Faruk TAN/Özlem Öztürk ÖZTAN				Signature					
	Approved by Sezgin PARMAKSIZ									
	Copy to	TH-YPLB		ÇMİ-MTk1		ÇMİ-ÜPB		ÇMİ-MÜT		
		ÇMİ-KGB		ÇMİ-MTk2		ÇMİ-MTk3		Other		

TECHNICAL EXPLANATION OF THE CHANGE

Issue The transition of the thermique cable socket to RAST5 in BLDC product

Explanation

- -For the BLCD products; an additional cable has been defined as in the new thermique cable RAST5 IDC socket is used.
- -In the combination of new and old motor additional cable 274700200 will be used.
- -In the combination of old and new motor aditional cable 274700100 will be used.
- -Cables and motors will be send together for a while, if after sale service is needed.

INSTALLATION METHOD

- -In case of the motor service cable; 2714700200 additional cable
- -In case of the service of the main cable; 2714700100 additional cable shall be submitted together for a while









INFORMATION ABOUT THE PART CHANGES

Ser.	New part(s)			Old Part(s)		
Ref	Part name	Stock number	Ref	Part name	Stock number	Code
1497	MOTOR POWER CABLE GR	27 1470 01 00				B2
1497	MOTOR POWER CABLE GR	27 1470 02 00				B2

CODE EXPLANATION :

- **A**-Old stocks can be used; Old & new parts are fully interchangeable
- B-Old stocks can be used; Old parts are interchangeable with old productions & new parts are interchangeable with new productions
- $extcolor{c}$ Old stocks can not be used. New parts are interchangeable with old & new productions
- D-Old stocks can not be used. New parts are interchangeable with new productions
- **E-**Old stocks can be used in old productions. New parts are interchangeable with old & new productions
- 1-Performance / 2-Production improvement / 3-Safety / 4-Material or dimension change / 5-Additional part / 6-Part cancellation / 7-Alternative use

No	Date	Brand	Model	Started from	Finished at	Signature
1						
2						
3						