KIT 436

AN 8 PIECE REPAIR KIT

BOARD #:

- BN44-00289B
- HV32HD-9SS

USED IN:

• SAMSUNG

FAULT SYMPTOM:

• DEAD QP802 & NT811S BLOWN

WHATS IN THE KIT:

- F801S
- NT811S
- BD801S
- QP802S
- RP821
- RP822
- DP802
- UP801S

We recommend all kits are fitted by qualified personnel & can accept no responsibility for loss, injury or damage caused by your use of this kit as a successful repair depends on the engineers own skill and fault finding ability.

FOR A REPAIR TO THIS BOARD PLEASE RING FOR A QUOTE