

KiT167

REPAIR KIT PSU & YSUS

42PC1DA
68719PT299/A
6871QTH053

FAULT SYMPTOM
DEAD - NO PICTURE, SOUND OK - SLOW TO
COME ON THEN NO PICTURE

©2011-2016 Ohm Supplies Ltd

DO NOT REPRODUCE

Produced for ASWO International Service GmbH

cct ref	description
FS2	T4A
C201	3300uF
C202	3300uF
C203	3300uF
C227	3300uF
C271	3300uF
C272	3300uF
C281	3300uF
C282	3300uF
C283	3300uF
IC18 - YSUS	YPPD-JO18E

SPECIALISED HEATING EQUIPMENT MAY BE
NEEDED TO REPLACE THE YSUS IC.